

Façade Inspections

Our services to curtain wall manufacturers in the design of their systems over the past 25 years have proven to be a valuable experience for the difficult and often complex investigations of curtain wall systems. A sample of some of our recent façade investigations include:

<p><u>The Bradley Center</u></p> <p>Project Type: Façade Inspections</p> <p>Client: The Bradley Center</p> <p>Location: Milwaukee, Wisconsin</p> <p>Description: This major sports facilities granite exterior cladding system had extreme sealant failure that resulted in water leakage.</p>	<p><u>Milwaukee Center Office Towers</u></p> <p>Project Type: Façade Inspections</p> <p>Client: Great Lake Reit</p> <p>Location: Milwaukee, Wisconsin</p> <p>Description: An extensive investigation and repair design was provided for the brick masonry façade of this 30 story complex.</p>
<p><u>Galtier Plaza</u></p> <p>Project Type: Façade Inspections</p> <p>Client: Zaidan Holdings Incorporated</p> <p>Location: Saint Paul, Minnesota</p> <p>Description: The 46 story building required an investigation and design of repairs to remediate leaking and structural deficiencies of the aluminum and glass curtain wall system.</p>	<p><u>Wisconsin Tower</u></p> <p>Project Type: Façade Inspections</p> <p>Client: Wisconsin Tower</p> <p>Location: Milwaukee, Wisconsin</p> <p>Description: The 22 story building dating back to the 1930's required a detailed investigation and repair design for the limestone façade after several panels fell from the upper floors.</p>

