

Remodeling

The following is a sampling of remodeling or rehabilitation projects where CSD provided engineering services.

<p><u>German/ American Building</u></p> <p>Project Type: Remodeling</p> <p>Location: Milwaukee, Wisconsin</p> <p>Description: Conversion to office space in this historic building required addition of a floor in a two story space leading to foundation underpinning and member reinforcement.</p>	<p><u>Iron Block Building</u></p> <p>Project Type: Remodeling</p> <p>Location: Milwaukee, Wisconsin</p> <p>Description: Restoration of this landmark building required a structural survey, structural reinforcement, and a new lateral load resisting system due to interior modifications.</p>	<p><u>Grain Exchange Building</u></p> <p>Project Type: Remodeling</p> <p>Location: Milwaukee, Wisconsin</p> <p>Description: Structural modifications were required to refurbish this historic building.</p>
<p><u>First Bank- Milwaukee</u></p> <p>Project Type: Remodeling</p> <p>Location: Milwaukee, Wisconsin</p> <p>Description: Exterior updating, entry changes and general renovation necessitated numerous structural modifications.</p>	<p><u>Germania Building</u></p> <p>Project Type: Remodeling</p> <p>Location: Milwaukee, Wisconsin</p> <p>Description: Settlement necessitated substantial underpinning and updated interior space required structural modifications.</p>	<p><u>Association of Commerce Building</u></p> <p>Project Type: Remodeling</p> <p>Location: Milwaukee, Wisconsin</p> <p>Description: Low strength concrete necessitated beam and column reinforcement for adequate load capacity.</p>

